



# Commercial GI Retrofits: Construction, Performance, and Maintenance

Ryan Winston, PhD, PE, Ohio State University

Erik Petrovskis, PhD, PE, Meijer Corporation

Don Carpenter, PhD, PE, Lawrence Technical University

Ian Simpson, EIT Ohio State University

Alec Grimm, Ohio State University

Ohio Stormwater Conference – Sharonville, OH

May 10, 2019

# Meijer Background



- 237 stores in six states
- 5 distribution centers and 6 food manufacturing plants



# Current LID/GI Practice

ST279 Manistee, MI:

- Test site for porous pavement
- Additional LID/GI practices
- **Cost competitive**
- **Comparable maintenance**




# Meijer Goals

- Document site data requirements for incorporating GI into the environmental site screening process.
  - Minimize overall data collection efforts and expenses during site screening and assist early site design efforts.
- GI site suitability manual, GI design guidance manual, and supporting documents and tools.
- Develop test case sites for GI
  - Collect performance/maintenance data

# Site Suitability – Meijer

## Site Suitability for Green Infrastructure Flowchart



**NOTE:** The flow chart does not represent a full set of considerations or questions on whether GI will meet local permitting requirements.

### LEGEND:



Green = Favorable condition for GI implementation.




Yellow = GI is possible but the design or regulatory approval process might be more difficult.



Red = Difficult condition for GI implementation.


# Site Suitability – Meijer



# Meijer Guidance Manual

- Introduction to GI techniques and tools for Meijer Site Adapt Civil Consultants
- Infiltration based GI design guidance and prototype elements
- Cost estimate information
- Maintenance information


# Bioswales



GI-5 BIOSWALE TYPICAL SECTION  
NTS



# Infiltration Basins






# Permeable Pavement



FOR EDGING OPTIONS SEE GI-12, GI-13, AND GI-14.




GI-16 UNILOCK HD-HIGH INFILTRATION PERMEABLE PAVER SECTION  
NTS





# Bioretention Cells





GI-1 PARKING LOT BIORETENTION CELL TYPICAL SECTION  
NTS



# Reynoldsburg Meijer



# Meijer Parking Lot Retrofit






# GI Design

## Permeable Pavement

## Bioretention






# Permeable Pavement Construction



# Initial Bioretention Design



G/—8

BIORETENTION CELL ON GRASS TYPICAL SECTION

NTS




# Site Soil Conditions




- Organic layer to 18"
- Clay soil below 18"
- Water table at ~5 ft bgs

# Changes to Design: High Water Table



GI-6 BIORETENTION CELL TYPICAL SECTION  
NTS

2 ft of  
separation  
from SHWT




GI-7 UNDERDRAIN DETAIL  
NTS



# Bioretention Construction



# GI Characteristics

| Characteristics   | Bioretention Cell | Permeable Pavement |
|---|-------------------|--------------------|
| Catchment area (ac)   | 1.49              | 1.02               |
|  <p>HYDRAULIC CEMENT WATERTIGHT CONNECTION</p> <p>SOLID (NON-PERFORATED) UNDERDRAIN ELBOW</p> <p>UNDERDRAIN 4" PERFORATED RIGID SCHEDULE 40 PVC OR SDR 35. 3/8" PERFORATED ON 12" CENTERS, 2 ROWS, @ 5 AND 7 O'CLOCK, RESPECTIVELY. 0.5% SLOPE MINIMUM.</p> <p>STONE DRAINAGE LAYER</p> <p>UNDERDRAIN</p> <p>24" FROM TOP OF CASING</p> <p>EXISTING CATCH BASIN</p> | 1                 | 92.2               |
|   | 3                 | 1641               |
|   |                   | 0                  |
|   |                   | 1575               |
|   | 1                 | 25:1               |
|   |                   | 0                  |
| Fill media depth (in)   | 2.5               | 0                  |
| Gravel thickness (ft)   | 1                 | 2.4                |
| IWS zone thickness (ft)   | 12                | 6                  |
| Underdrain diameter (in)  | 4                 | 4                  |
| Vegetation  | Shrubs and Forbs  | None               |




# Monitoring Design



# Monitoring Design

- Tipping bucket & manual rain gauges
- Weir & pressure transducer in 4 catch basins
  - Weir equation used to determine hydrograph
- 1-minute interval measurements



# Project Timeline




- Monitoring equipment installed Oct 2016
  - Data collection consistent throughout project
- 3 week construction window
- Baseline and retrofit monitoring periods both ~1 year






# Observed Rainfall Events





# Runoff Volume

## Bioretention





# Runoff Volume

## Bioretention


| Period       | Rainfall<br>(in) | Bioretention<br>Outlet (in) | %<br>Reduction |
|--------------|------------------|-----------------------------|----------------|
| Baseline     | 33.04            | 30.74                       | 7.0            |
| Construction | 4.33             | 1.84                        | 57.4           |
| Retrofit     | 24.31            | 6.61                        | 72.8           |






# Runoff Volume with Time

## Bioretention



# Runoff Volume

## Permeable Pavement





# Runoff Volume


## Permeable Pavement

| Period       | Rainfall<br>(in) | Perm. Pave.<br>Outlet (in) | %<br>Reduction |
|--------------|------------------|----------------------------|----------------|
| Baseline     | 33.04            | 30.35                      | 8.2            |
| Construction | 4.33             | 3.99                       | 7.9            |
| Retrofit     | 36.02            | 31.82                      | 11.7           |



# Peak Flow

## Bioretention




### Period

- Baseline
- Construction
- Retrofit



# Peak Flow

## Permeable Pavement




# Practical Challenges



- SOP for plow drivers:
  - Move snow as far from store as possible
  - Often adjacent to parking lot islands
  - Near drain to prevent re-freeze
  - Particularly for bioretention, created a storage spot for them!



# Surface Infiltration Rate Testing



- Quarterly testing at 6 locations
  - Inform maintenance
  - Hot spots for clogging




# Maintenance Test

- Site was 17 months old at time of maintenance
  - No previous maintenance
  - Moderately clogged (5-150 in/hr)
  - Maintenance performed April 25, 2019
  - 5-15 passes with regenerative air street sweeper
  - Maintenance took 45 mins + 15 mins to add new chip stone






# Maintenance



Clogged Area



Clogged +  
Snow Storage



Cleaned



# Maintenance Results

## ASTM Test

| Location | Date      | Inf Rate (in/hr) | 4/25/19<br>Maintenance | Date      | Inf Rate (in/hr) |
|----------|-----------|------------------|------------------------|-----------|------------------|
| 1        | 4/24/2019 | 27.7             |                        | 4/30/2019 | 2.1              |
| 2        |           | 142.3            |                        |           | 10.4             |
| 3        |           | 5.7              |                        |           | 4.2              |
| 4        |           | 44.8             |                        |           | 9.7              |
| 5        |           | 53.8             |                        |           | 35.2             |
| 6        |           | 27.8             |                        |           | 10.5             |

## Simple Infiltrometer

| Location | Date      | Inf Rate (in/hr) | 4/25/19<br>Maintenance | Date      | Inf Rate (in/hr) |
|----------|-----------|------------------|------------------------|-----------|------------------|
| 1        | 4/24/2019 | 20.7             |                        | 4/30/2019 | 7.2              |
| 2        |           | 144.7            |                        |           | 25.5             |
| 3        |           | 5.2              |                        |           | 5.7              |
| 4        |           | 24.4             |                        |           | 10.9             |
| 5        |           | 92.0             |                        |           | 55.9             |
| 6        |           | 26.1             |                        |           | 11.6             |

# Summary of Maintenance

- Decline in infiltration rate following maintenance at 5/6 testing locations
  - Have not observed this in ~5 rounds of pre/post infiltration testing since 2014 when using a regenerative air sweeper
  - Perhaps related to rain during maintenance?



# The Path Forward...

- Continue to monitor and maintain GI at Reynoldsburg store in support of Meijer's sustainability mission
- Does bioretention performance get better with time?
- Understand long-term permeable pavement maintenance frequency/cost
- See you at a future OH SWC!





# Questions?

More Information:  
[Winston.201@osu.edu](mailto:Winston.201@osu.edu)