

CASE STUDIES FOCUSED ON LONG TERM INSPECTION AND MAINTENANCE OF POST-CONSTRUCTION BMP'S IN HAMILTON COUNTY

Hamilton County Planning + Development
Stormwater + Infrastructure Division

Mohammad M Islam PE
Ben Poole EIT





POST CONSTRUCTION BMP's

1. Long Term Performance
2. Maintenance
3. Enforcement


HISTORY HAMILTON COUNTY STORM WATER REGULATIONS

1. Hamilton County Storm Water Drainage System Regulations
 - Water Quantity Requirements
2. Post Construction Water Quality Regulations.
3. Stream Corridor Regulations

Major Elements of Hamilton County Storm Water Drainage System “SDS” Regulations

1. Detention required on all development redevelopment
2. Design requirements for both minor and major systems (i.e.. Flood routing)
3. Regulations apply to both public and private drainage systems.

TOWNSHIPS AND MUNICIPALITIES



Responsibilities


Plan Review/Approval:

- ▣ ODOT - Highways
- ▣ HCE - County Roads
- ▣ P&D - All Others

Operation & Maintenance:

- ▣ ODOT - Highways
- ▣ HCE - County Roads
- ▣ P&D & Townships
split systems on
township roads.
- ▣ Private - Owner

What does each Permit Require for Post Construction?



Permit Flowchart

Project

Submit Preliminary Plan showing BMP Locations

**Develop Final Plan with Storm Water Management System, BMP, SWP3,
and O&M Plan**


MS4 Approval after necessary plan revisions

**Inspect Post Construction BMP during
construction**

**Submit Notice of
Intent to OEPA**

Annual Inspections

DETENTION BASINS AND POST CONSTRUCTION BMP'S IN HAMILTON COUNTY



TYPES OF POST CONSTRUCTION BMPS APPROVED

65 – Dry Extended Detention

48 – Underground Detention

16 – Dry Wells

15 – Inlet Filters (4 sites)

6 – Wet Extended Detention


6 – Raingarden/Bioretentions

4 – Infiltration Basin/Trench

4 – Pervious Pavement

3 – Hydrodynamic Separators

1 – Rainwater Cistern



POST-CONSTRUCTION STRUCTURAL BEST MANAGEMENT PRACTICES



Raingarden



Retention Pond

Example Post-Construction BMP's

Structural Post Construction BMPs

Pervious Pavement

Background Information

- Temporarily store runoff, allowing pollutant filtration and groundwater infiltration.
- Discharge water through infiltration or underdrain.
- Can be used independently, for runoff reduction, or in conjunction with other BMPs



Structural Post Construction BMPs

Infiltration Practices

Background Information

- Treat storm water through a filtering substrate (sand, gravel or soil).
- Discharges into the ground water.
- Requires appropriate soils and geology to ensure success.



Infiltration
Trench Area



Structural Post Construction BMP's

Dry Extended Detention Basin

Background Information

- Detains and releases run-off WQv slowly over 48 hours
- Two methods are available:
 - Above ground – Preferred method when feasible.
 - Below ground – Useful in urban/specific situations.



Structural Post Construction BMP's

Wet Extended Detention Basin (Retention)

Background Information

- Capture and release 100% of the WQv slowly over 24 hours (outlet control required)
- Provides permanent storage for at least 100% of the WQv.
- The full storage depth ranges from 3-6 feet .



Structural Post Construction BMP's

Bioretention

Background Information

- Treats storm water via specific soils.
- Uses a perforated underdrain or catch basin as an outlet.
- Specially selected plant species utilized to maximize treatment/infiltration and provide the appearance of normal landscaping.
- Designed to store 100% of the WQv prior to filtration.
- Total filtration should occur within 48 hours.



Post Construction BMP Inspection

- ▣ Compile report of all BMPs using GIS database.
- ▣ Generate inspection sheet for each BMP.
- ▣ Inspection performed and pictures taken.
- ▣ Inspection results added to existing database.
- ▣ Letters sent to owners of BMPs that need maintenance.
- ▣ BMP scored on a scale 0-3 in 13 categories
- ▣ 0 – Good Condition
- ▣ 1 – Acceptable, monitor for future issues
- ▣ 2 – Needs maintenance
- ▣ 3 – Immediate maintenance/repair needed
- ▣ Comments section provided to record details for each inspection category.

BMP Inspection Scoresheet

Storm Water Post-Construction BMPs INSPECTION CHECKLIST Hamilton County Department of Planning & Development

PWSD Number:			Post-Construction BMP		Score:
Project Name:			No Post-Construction BMP		
Inspection Date:					
Inspector:					
Address:					
N/A = Not Applicable 0 = In Compliance (No Issues) - Good Condition 1 = Monitor For Future Problems - Acceptable Condition 2 = Routine Maintenance – Need Improvement 3 = Immediate Maint. Or Repair Needed – Bad Condition					
Structure Type(s):					
	Dry Basin		Device-Contech Type Product		Rain Garden
	Wet Basin		Underdrain		Infiltration Basin
	Inline Pipe		Drywell		Pervious Pavement
	Stormtech System		Inlet Filters		Swale/Strip BMP
					Media Filter
					Biofilter
					Constructed Wetland
					Other
		Control Structure	Comments		
Item No	Type:				
	Description:				
1	Trash Present:				
2	Any Erosion:				
3	Grass/Ground Cover Condition:				
4	Standing Water (More than 3 days in pond):				
5	Displaced Rip Rap:				
6	Grease/Oil Present				
7	Emerg. Spillway Clear of Debris:				
8	Inlet Clear of Debris:				
9	Outfall Clear of Debris:				
10	Low Flow Orif. Clear of Debris or Clogged:				
11	Structure Sumps Greater Than 50% Full of Sediment:				
12	Underdrain/Dewatering System Functioning:				
13	Post-Constr. Standpipe Clean/Functioning:				
14	Other (Specify in Comments):				
Total Score:					


Mercy West Hospital

- ▣ Dry Detention Pond & Underground Detention
- ▣ Dry basin built in 2011
- ▣ Underground basin converted from dry basin in 2016
- ▣ Treat 11 acre and 20 acre drainage areas




Mercy West Hospital – Dry Basin

- ▣ Total Volume = 49,400 cf
- ▣ $WQ_v = 19,453$ cf
- ▣ Inspection Scores:
 - 2015 – 6
 - 2017 – 6
 - 2018 – 12
- ▣ Inlet/Outlet clogging and sediment issues ongoing.
- ▣ Trash, erosion, and ground cover issues in 2017 & 2018.
- ▣ 2" orifice in face of Outlet Control Structure (OCS).



Mercy West Hospital – Underground System

- ▣ Converted from dry basin in 2016 to add additional parking
- ▣ Total Volume = 131,432 cf
- ▣ $WQ_v = 35,283$ cf
- ▣ Inspection Scores:
 - 2018 – 0
- ▣ Largest underground detention system in Hamilton County
- ▣ No maintenance issues.
- ▣ 2.5" orifice in internal weir wall of OCS.




Mercy West Hospital – Underground System



Artis Senior Living

- ❑ Dry detention basin installed in 2015.
- ❑ Total Volume = 24,113 cf
- ❑ $WQ_v = 8,471$ cf
- ❑ Inspection Scores:
 - 2017 – 12
 - 2018 – 6
- ❑ Erosion, overgrown vegetation, sedimentation, inlets & outlets clogged.
- ❑ Control structure condition improved 2017-2018.
- ❑ 4" perforated pipe under washed gravel WQ control.



Artis Senior Living



October 2016




*October
2018*



Blue Ash Self Storage

- ▣ 1 Dry Detention Basin and 1 Infiltration Trench installed in 2013.
- ▣ Treat an 8 acre site




1. SEDIMENT SHALL BE PREVENTED FROM ENTERING THE INFILTRATION TRENCH. SEDIMENT CLOGGING AND SEALING OFF THE PERMEABLE SOIL IS THE MOST COMMON CAUSE OF INFILTRATION TRENCH FAILURE. RUNOFF FROM THE CONSTRUCTION SITE SHALL NOT BE ALLOWED TO FLOW TO TRENCH UNTIL CONSTRUCTION IS COMPLETE AND SLOPE AREAS HAVE BEEN STABILIZED. IF STORM DRAINS ENTER THE INFILTRATION TRENCH DIRECTLY AND CANNOT BE REDIRECTED, THEY SHALL BE SEALED WITH A MASONRY PLUG LINE. ALL CONTRIBUTING DRAINAGE AREAS ARE STABILIZED.
2. THE INFILTRATION TRENCH DESIGN SHALL INCLUDE A SYSTEM FOR REDUCING SEDIMENT FROM STORMWATER BEFORE IT ENTERS THE INFILTRATION STRUCTURE. HOWEVER, THIS SYSTEM SHALL NOT BE USED TO CONTROL SEDIMENT DURING CONSTRUCTION.
3. TRENCH EXCAVATION AND BACKFILLING OF SANDS AND ROCK SHALL BE DONE WHEN THE SOIL MOISTURE IS LOW ENOUGH TO ALLOW THE SOIL TO CRACK OR FRACTURE. NO TRENCH EXCAVATION OR FILL SHALL OCCUR ON WET SOIL TO PREVENT COMPACTION AND MAINTAIN SOIL PERMEABILITY.
4. BOTTOM SAND FILTER- THE BOTTOM OF THE TRENCH SHALL BE COVERED WITH AN 8-INCH LAYER OF CLEAN SAND. THE SAND LAYER SHALL BE PLACED THE SAME DAY EXCAVATION IS COMPLETED.
5. GEOTEXTILE- THE SIDES AND TOP OF THE TRENCH SHALL BE LINED WITH GEOTEXTILE. THE BOTTOM OF THE TRENCH SHALL NOT BE COVERED WITH GEOTEXTILE.
6. ROCK- ROCK FILL SHALL BE CLEAN, POORLY-GRADED, UNIFORM SIZE CRUSHED WASHED ROCK. WELL-GRADED ROCK HAS LESS VOID SPACE AVAILABLE FOR RUNOFF STORAGE AND SHALL NOT BE ACCEPTED.
7. GRAVEL TOP LAYER- THE TOP LAYER OF THE GEOTEXTILE SHALL BE COVERED BY 8 INCHES OF GRAVEL (0.75- INCH DIAMETER).



Blue Ash Storage – Dry Basin

- ❑ Total Volume = 25,591 cf
- ❑ $WQ_v = 6,400$ cf
- ❑ Inspection Scores:
 - 2015 – 8
 - 2017 – 25
 - 2019 – 23
- ❑ Sediment Basin standpipe was never switched to Post Construction Water Quality Control.
 - Prevented the basin from functioning as a dry basin
 - Oversight/miscommunication between agencies/inspectors.
- ❑ Inlets clogged, trash, and overgrown vegetation are ongoing issues.



Blue Ash Storage – Dry Basin

*October
2015*



*March
2018*



Blue Ash Storage – Infiltration Trench


- ▣ Redeveloped WQv treated = 288 cf
- ▣ 6" underdrain outlet
- ▣ Inspection Scores:
 - 2015 – 0
 - 2018 – 1
- ▣ 2018 - Minor sediment deposits in gravel



*October
2015*




*December
2018*



Alois Alzheimer Center

- ❑ 1 Dry Detention Basin installed in 2010.
- ❑ 8.11 ac drainage area
- ❑ Total Volume = 15,390
- ❑ $WQ_v = 4,792$
- ❑ Inspection Scores:
 - 2015 - 12
 - 2017 - 13
 - 2018 - 19
- ❑ Erosion, ground cover, WQ control and standing water are ongoing issues.



Alois Alzheimer Center



*October
2015*



*December
2018*



Crossroads Church

- ▣ 1 Wet Basin, 1 Dry Basin
- ▣ Installed in 2016
- ▣ Both basins treating roughly 3 acres.
- ▣ WQ controls are 1.65" and 1" orifice in the face of the OCS.



Crossroads Church – Wet Basin

- ▣ Inspection Score:
 - 2018 – 0
- ▣ No issues, in great condition.



Outlet Pipe installation – August 2016



September 2016



*October
2018*

Crossroads Church – Dry Basin

▣ Inspection Scores:

- 2017 – 4
- 2018 – 2

- ▣ Erosion and overgrown vegetation issues in 2017.
- ▣ Vegetation only issue in 2018.




*March 2017
(after heavy
rain)*



October 2018

Liberty Nursing

- Dry Detention Basin installed in 2014
- 6.5 ac drainage area
- Total Volume = 15,000 cf
- $WQ_v = 5,875$ cf
- 4" perforated pipe under washed gravel
- Inlet/Outlet/WQ Control clogged, erosion, vegetation, sediment, and standing water issues all 3 years.



Inspection Scores:

- 2015 – 12
- 2017 – 22
- 2018 – 23

Liberty Nursing



October 2015



December 2018


Diamond Oaks

- ❑ Rain Garden with Pervious Pavement
- ❑ Rainwater Collection System
- ❑ Both Installed in 2011
- ❑ 2.23 acre drainage area to rain garden
- ❑ Rainwater collected from 0.13 acres of roof used for irrigation.



Diamond Oaks – Rain Garden

- Inspection Scores:
 - 2015 – 0
 - 2017 – 0
 - 2018 – 0
- Pervious pavement drains into rain garden.
- Rain garden drains through underdrain and catch basin 6" above grade.




2011



2018



*Underdrain
Installation*



Rainwater Cistern

- ▣ Collects all downspout runoff from a 5,600 sf building addition.
- ▣ School uses rainwater for irrigation.




Roof Garden




2018 Inspection Results

Score by Category




2018 Inspection Results



*Denotes 5 or less inspected

- Dry detention problems generally caused my lack of basic maintenance and small WQ/Low-flow orifices.
- Wet detention basins fare much better than dry basins.
- Inlet filters (no longer acceptable with 2018 CGP) were all removed or completely clogged.



Questions and Answers

